




## Инструкция по сборке ПСМ-500 Подкатной стол металлический



**2x**




**2x**



**1x**




**1x**




<p><b>4x</b></p> <p>1x10</p>	<p><b>4x</b></p> <p>2x10</p>	<p><b>12x</b></p> <p>10x20</p>	<p><b>8x</b></p> <p>5x55</p>	<p><b>4x</b></p> <p>40x40</p>
<p><b>4x</b></p> <p>35x35</p>	<p><b>1x</b></p>	<p><b>2x</b></p> <p>ESD</p>	<p><b>2x</b></p> <p>ESD</p>	


**1**



2



3



4

