







## Инструкция по сборке СПП Стол промышленный металлический




2x 2x10 	8x 1x10 	12x 10x20 	10x 5x55 	4x 6x50 
4x 	6x 	4x 40x40 	4x 40x80 	1x 




4



5



6



7

